
RHIC Physics fy04 Run Yellow Ring Main Power Supplies 1004B


(Note: Phase Lock Loop Fault caused the Blue & Yellow to QLI at the same time, sharing one quench = 0.5ea.)



Reported Fault Causes and Associated Main Power Supply

RHIC Physics fy04 Run Blue Ring Main Power Supplies 1004B


(Note: Phase Lock Loop Fault caused the Blue & Yellow to QLI at the same time, sharing one quench = 0.5ea.)




Reported Fault Causes and Associated Main Power Supply

RHIC PHYSICS FY04 RUN


Most Significant Magnets that had been Quenched 2 or more Times




RHIC Physics fy04 - Main QLI Percentage of Faults




Snake and Spin Rotator Quench Faults RHIC Polarized Proton Run fy04



Corrector Power Supply Replacements



RHIC Physics fy04 Corrector Power Supply Replacements per Alcove



Location by Alcove / Serial Number Removed